

## Driver\_install\_Readme.txt

### \*\*Windows 10 OS\*\*

- No additional Drivers are needed to be installed under Windows 10  
Windows has already a built-in Default Driver that will allow Radio to operating with under CPS Utility

### \*\*Windows 7/8/Vista OS\*\*

- Important - Windows 7/8/Vista confirm your OS 32 or 64bit version.
- 32bit OS, open the x68 folder and install "USB Virtual Com Port Driver.exe"
- 46bit OS, open the x64 folder and install "USB Virtual Com Port Driver.exe"