


Exploded View & Miscellaneous Parts



| REF. | VXSTD P/N | Description | Qty. |
|------|---------------------|----------------------------|------|
| ① | U44104002 | TAPTITE SCREW M2X4NI | 10 |
| ② | U44104002 (VX-180U) | TAPTITE SCREW M2X4NI | 2 |
| ③ | U20206007 | BINDING HEAD SCREW M2.6X6B | 2 |
| ④ | U24110002 | TAPTITE SCREW M2X10NI | 2 |
| ⑤ | U02206007 | SEMS SCREW SM2.6X6B | 2 |
| ⑥ | U00103002 | PAN HEAD SCREW M2X3NI | 1 |

CAUTION

The mic element must be desoldered and removed from the PCB on order to re-install its protective rubber cover.

Therefore, be careful not to remove this cover unless mic element replacement is necessary.